




GENERAL NOTES

- A. RECONFIGURE PATHWAYS CONNECTING FOREST ROAD TO THE COMMON AND TO THE MEETINGHOUSE. INSTALL LAMP POSTS ALONG THE PATH THAT MATCH THE LAMP POSTS IN THE TOWN CENTER.
- B. INSTALL A NEW BUILDING SIGN ALONG FOREST ROAD.
- C. RECONFIGURE PARKING, GENERATING DEFINED SPOTS AND LIMITING DRIVE-THRU ACCESS FROM SAWMILL TO FRANCESTOWN RD. CONSULT A CIVIL ENGINEER FOR PARKING LOT CONFIGURATION.
- D. RE-GRADE THE LAND DIRECTLY TO THE NORTH OF THE BUILDING TO MITIGATE WATER INFILTRATION.
- E. CONSTRUCT A NEW ENTRY AND PERFORMANCE TERRACE AT THE SOUTH OF THE BUILDING, WITH AN INTEGRATED, ACCESSIBLE RAMP PROVIDING ACCESS INTO THE BUILDING. INSTALL NEW PLANTERS BETWEEN THE BUILDING AND THE TERRACE.
- F. PROVIDE ELECTRICAL AND POWER UPGRADES TO SUPPORT THE PERFORMANCE TERRACE, SITE UPGRADES AND TOWN NEEDS.



SITE PLAN
GREENFIELD MEETINGHOUSE
MISIASZEK TURPIN PLLC - 2019







LOWER LEVEL FLOOR PLAN GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019

GENERAL NOTES

- INSTALL A MODERN, ACCESSIBLE ELEVATOR, LOCATED TO LIMIT IMPACT ON HISTORIC FABRIC.
- UPGRADE FINISHES WITHIN THE COMMUNITY ROOM, INCLUDING WALL, CEILING AND COLUMN PAINT, AND FLOOR TILES. ALL DUCTS TO BE RELOCATED TO THE PERIMETER OF THE CEILING.
- NEW ACCESSIBLE RESTROOMS TO BE CONSTRUCTED, WITH MODERN, EFFICIENT FIXTURES.
- RECONFIGURE THE KITCHEN, WITH UPGRADED CABINETRY AND APPLIANCES.
- NEW MAINTENANCE ROOM TO BE CONSTRUCTED WITH SERVICE SINK AND BUILT-IN SHELVING TO ACCOMMODATE THE BUILDING'S MAINTENANCE REQUIREMENTS.
- EXISTING WOODEN STAIR TO BE REFINISHED WITH NEW WOOD HANDRAIL INSTALLED AT INNER PERIMETER. REMOVE PORTION OF WALL ENCLOSING BASE OF STAIR AND INSTALL NEW OPEN RAILING. CONSTRUCT NEW ENCLOSURE WITH DOOR.
- INSTALL NEW INSULATION AND FINISHED GYPSUM BOARD WITHIN THE EASTERN EGRESS VOLUME, ALONG WITH A NEW HANDRAIL.
- INSTALL NEW INSULATION AND FINISHED GYPSUM BOARD WITHIN THE WESTERN EGRESS VOLUME, AND RECONFIGURE THE STAIRS TO BETTER CONFORM WITH BUILDING CODE.
- CONSTRUCT NEW BENCH WITH INTEGRATED COAT HOOKS AT THE WESTERN ALCOVE.
- REFERENCE RFS REPORT FOR ELECTRICAL, MECHANICAL AND FIRE SUPPRESSION SYSTEM UPGRADES FOR THE BUILDING.
- RESTORE THE THREE HISTORIC TRANSOM WINDOWS THAT REMAIN AND REPAIR THE EXTERIOR WINDOW WELLS AND SLOPED COVERS.







GENERAL NOTES

- A. INSTALL A MODERN, ACCESSIBLE ELEVATOR, LOCATED TO LIMIT IMPACT ON HISTORIC FABRIC.
- B. REMOVE DIVIDING WALL IN THE FOYER, CONSTRUCT A NEW WALL AT THE EAST OF THE RESTROOM.
- C. REMOVE EXISTING DOOR TO THE LOWER LEVEL, AND INSTALL AT NEW EASTERN WALL OF THE RESTROOM.
- D. REFINISH EXISTING STAIRS LEADING TO THE UPPER LEVEL AND REMOVE EXISTING CHAIR-LIFT AND CARPET. INSTALL NEW CENTRAL CARPET RUNNER AND REFINISH WOODWORK.
- E. RESTORE ALL INTERIOR FINISHES WITHIN THE MEETING HALL AND STAGE. RESTORE ALL WINDOWS AND INTERIOR SHUTTERS.
- F. CONSTRUCT NEW ENTRANCE & PERFORMANCE TERRACE AT THE SOUTH OF THE BUILDING.

MAIN LEVEL FLOOR PLAN
GREENFIELD MEETINGHOUSE
MISIASZEK TURPIN PLLC - 2019





GENERAL NOTES


- INSTALL A MODERN, ACCESSIBLE ELEVATOR, LOCATED TO LIMIT IMPACT ON HISTORIC FABRIC.
- UPGRADE AND RESTORE FINISHES WITHIN THE SANCTUARY, INCLUDING PAINTING THE PLASTER WALLS, CLEANING THE TIN CEILING, REMOVING THE CARPET AND REFINISHING THE WOOD FLOORS.
- REMOVE DUCT ENCLOSURE AT NORTHWEST CORNER AND INTEGRATE MECHANICAL DUCT & GRILLS AT BASE OF RAISED ALTAR.
- RECONFIGURE TOP OF STAIR ENCLOSURE WITHIN THE NARTHEX.
- RAISE THE SOUTHWESTERN CORNER OF THE NARTHEX FLOOR TO BE LEVEL WITH THE SANCTUARY FLOOR; COORDINATE ELEVATOR ACCESS WITH MODIFIED FLOOR ELEVATION.
- CONSTRUCT A NEW ACCESSIBLE RESTROOM, AT THE SAME FLOOR ELEVATION AS THE SANCTUARY AND ELEVATOR LOBBY. RESTROOM TO HAVE MODERN, EFFICIENT FIXTURES.
- INSTALL HISTORIC DOUBLE DOORS AT THE MAIN, CENTRAL ENTRANCE TO THE SANCTUARY.
- RESTORE ALL STAINED-GLASS WINDOWS.


UPPER LEVEL FLOOR PLAN GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019



SCALE: 1/8" = 1'-0"





GENERAL NOTES

- A. INSTALL A MODERN, ACCESSIBLE ELEVATOR, LOCATED TO LIMIT IMPACT ON HISTORIC FABRIC.
- B. UPGRADE FINISHES WITHIN THE LOFT, INCLUDING WALL & CEILING PAINT, AND INSTALL NEW FLOORING; REPAIR WHERE DAMAGED.
- C. RECONSTRUCT THE SOUTHWESTERN CORNER OF THE FLOOR.
- D. CLEAN AND RESTORE THE SLIDING BEADBOARD PARTITION, MAKING BOTH PANELS ONCE AGAIN OPERABLE.
- E. REMOVE SECTION OF FLOORING IMMEDIATELY ADJACENT TO THE FOUR STAINED-GLASS WINDOWS. INSTALL BEADBOARD RAIL AT PERIMETER OF THE OPENING TO PROVIDE SAFETY TO USERS AND SAFETY FOR THE HISTORIC GLASS.
- F. RECONFIGURE STAIRWAY TO ACCOMMODATE NEW WINDOW WELLS. STAIRS TO HAVE CENTRAL NON-SLIP TREAD AND A WOOD HANDRAIL INSTALLED AT THE INNER PERIMETER. COORDINATE PARTIAL WALL AT LOFT WITH STAIR RECONFIGURATION.
- F. INSTALL A NEW, RETRACTABLE LADDER TO ACCESS THE ATTIC.

LOFT LEVEL FLOOR PLAN


GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019



SCALE: 1/8" = 1'-0"





GENERAL NOTES

- COORDINATE MINOR MODIFICATIONS WITH THE INSTALLATION OF THE MODERN, ACCESSIBLE ELEVATOR.
- RECONSTRUCT THE CENTRAL FLOOR OF THE ATTIC AND INSTALL RAILINGS WITH INTEGRATED GATE AT THE NORTHERN EDGE.
- INSTALL A CATWALK, PROVIDING ACCESS TO THE ENTIRE SPACE.
- EXTEND NEW FLOORING TO EAST & WEST OF THE CENTRAL FLOOR, PROVIDING SAFER STORAGE SPACE.
- RECONSTRUCT LADDERS AND ACCESS TO THE CLOCKROOM AND THE BELL TOWER.
- PROVIDE INCREASED INSULATION THROUGHOUT THE SPACE.
- REFERENCE RFS REPORT FOR ELECTRICAL AND FIRE SUPPRESSION UPGRADES FOR THE ATTIC SPACE.
- RESTORE THE TWO HISTORIC WINDOWS WITHIN THE ATTIC.


ATTIC LEVEL FLOOR PLAN


GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019



SCALE: 1/8" = 1'-0"





GENERAL NOTES


- A. MAKE REPAIRS TO HISTORIC FABRIC WHERE NECESSARY.
- B. RECONSTRUCT LADDERS, PLATFORMS AND ACCESS TO THE CLOCKROOM AND THE BELL TOWER.
- C. REFERENCE RFS REPORT FOR ELECTRICAL AND FIRE SUPPRESSION UPGRADES WITHIN THE BELL TOWER.
- D. RESTORE THE HISTORIC WINDOW WITHIN THE CLOCKROOM.
- E. RE-ROOF THE EASTERN AND WESTERN EGRESS VOLUMES, PROVIDING INCREASED INSULATION AND WATER PROTECTION.
- F. RE-ROOF THE NORTHERN STORAGE VOLUME, PROVIDING INCREASED INSULATION AND WATER PROTECTION.


BELL TOWER & ROOF PLAN
GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019



SCALE: 1/8" = 1'-0"





GENERAL NOTES

- A. INSTALL WATER BARRIER AND INSULATION SYSTEM AT FULL PERIMETER OF THE FOUNDATION.
- B. RESTORE AND REPLACE, WHERE ROT AND DAMAGE IS BEYOND REPAIR, ALL CLAPBOARD, TRIM AND WOODWORK ON THE EXTERIOR OF THE BUILDING.
- C. RE-GLAZE AND RE-PUTTY ALL HISTORIC WINDOWS, AND INSTALL NEW STORMWINDOWS AT THE EXTERIOR.
- D. INSTALL A NEW WINDOW AT THE WESTERN EGRESS VOLUME, TO REPLICATE THE HISTORIC WINDOW THAT WAS ORIGINALLY THERE.
- E. RE-FINISH PAIR OF HISTORIC ENTRY DOORS, AND INSTALL NEW SIX-PANEL DOORS WOODEN AT ALL OTHER LOCATIONS.
- F. RECONSTRUCT THE OCTAGONAL, UPPER PORTION OF THE BELL TOWER IN ITS ENTIRETY; NEW CONSTRUCTION TO MATCH EXISTING.
- G. CONSTRUCT NEW PERFORMANCE TERRACE, INTEGRATED WITH THE SURROUNDING TERRAIN OF THE COMMON; INCLUDE NEW PLANTERS AND ACCESSIBLE RAMP.

SOUTH ELEVATION
GREENFIELD MEETINGHOUSE

MISIASZEK TURPIN PLLC - 2019

SCALE: 3/32" = 1'-0"







GENERAL NOTES

- A. INSTALL WATER BARRIER AND INSULATION SYSTEM AT FULL PERIMETER OF THE FOUNDATION.
- B. RESTORE AND REPLACE, WHERE ROT AND DAMAGE IS BEYOND REPAIR, ALL CLAPBOARD, TRIM AND WOODWORK ON THE EXTERIOR OF THE BUILDING.
- C. RE-GLAZE AND RE-PUTTY ALL HISTORIC WINDOWS, AND INSTALL NEW STORMWINDOWS AT THE EXTERIOR.
- D. RE-FINISH PAIR OF HISTORIC ENTRY DOORS, AND INSTALL NEW SIX-PANEL DOORS WOODEN AT ALL OTHER LOCATIONS.
- E. RECONSTRUCT THE OCTAGONAL, UPPER PORTION OF THE BELL TOWER IN ITS ENTIRETY; NEW CONSTRUCTION TO MATCH EXISTING.
- F. CONSTRUCT NEW PERFORMANCE TERRACE, INTEGRATED WITH THE SURROUNDING TERRAIN OF THE COMMON; INCLUDE NEW PLANTERS AND ACCESSIBLE RAMP.

EAST ELEVATION
GREENFIELD MEETINGHOUSE
MISIASZEK TURPIN PLLC - 2019

SCALE: 3/32" = 1'-0"





GENERAL NOTES

- A. INSTALL WATER BARRIER AND INSULATION SYSTEM AT FULL PERIMETER OF THE FOUNDATION.
- B. RESTORE AND REPLACE, WHERE ROT AND DAMAGE IS BEYOND REPAIR, ALL CLAPBOARD, TRIM AND WOODWORK ON THE EXTERIOR OF THE BUILDING.
- C. RE-GLAZE AND RE-PUTTY ALL HISTORIC WINDOWS, AND INSTALL NEW STORMWINDOWS AT THE EXTERIOR.
- D. RE-FINISH PAIR OF HISTORIC ENTRY DOORS, AND INSTALL NEW SIX-PANEL DOORS WOODEN AT ALL OTHER LOCATIONS.
- E. RECONSTRUCT THE OCTAGONAL, UPPER PORTION OF THE BELL TOWER IN ITS ENTIRETY; NEW CONSTRUCTION TO MATCH EXISTING.

NORTH ELEVATION
GREENFIELD MEETINGHOUSE
MISIASZEK TURPIN PLLC - 2019





GENERAL NOTES

- A. INSTALL WATER BARRIER AND INSULATION SYSTEM AT FULL PERIMETER OF THE FOUNDATION.
- B. RESTORE AND REPLACE, WHERE ROT AND DAMAGE IS BEYOND REPAIR, ALL CLAPBOARD, TRIM AND WOODWORK ON THE EXTERIOR OF THE BUILDING.
- C. RE-GLAZE AND RE-PUTTY ALL HISTORIC WINDOWS, AND INSTALL NEW STORMWINDOWS AT THE EXTERIOR.
- D. RE-FINISH PAIR OF HISTORIC ENTRY DOORS, AND INSTALL NEW SIX-PANEL DOORS WOODEN AT ALL OTHER LOCATIONS.
- E. RECONSTRUCT THE OCTAGONAL, UPPER PORTION OF THE BELL TOWER IN ITS ENTIRETY; NEW CONSTRUCTION TO MATCH EXISTING.
- F. CONSTRUCT NEW PERFORMANCE TERRACE, INTEGRATED WITH THE SURROUNDING TERRAIN OF THE COMMON; INCLUDE NEW PLANTERS AND ACCESSIBLE RAMP.

WEST ELEVATION
GREENFIELD MEETINGHOUSE
MISIASZEK TURPIN PLLC - 2019

